
MD Picture Process Maps -Salvage

MD Manual Tie Baler Operation

Required Tools and Materials								
	Daily Checklist		Key					

The Manual Tie Baler consists of three pieces:


- ✓ Gaylord Tipper: Tips the Gaylord to deposit items onto the Conveyor Belt
- ✓ Conveyor Belt: The product moves across the Conveyor Belt, heading toward the Baler. While on the Conveyer Belt, items can be sorted, and inappropriate items are removed.
- ✓ Baler: The Baler compacts the product so that it can be bound together with baling wire.



Baler Start Up

- 1. Turn the **Baler Toggle Switch** *On* (90° Counter Clockwise)
- 2. Turn the **Baler Key** to *On* (This turns on the Information Screen)
- 3. Press the **Auto On** button to start the Baler







2. Baler Key —
Emergency Stop

3. Push to Start button

The stack light flashes orange while the Baler is in operation.



1. Baler Toggle Switch

Information screen

Baler Start Up

From the Information Screen:

- 4. Press and hold the **Auto On** button for 20 seconds and wait for the motor to turn on.
- 5. Press the **Conveyor Disabled** button to enable the conveyor. The Baler should already be set to *Long Bale*.



Loading The Product

NOTE:

Before loading, ensure the Tipper is empty.





 With a Pallet Jack, place the Gaylord of product into the Tipper.

NOTE:

Both the Gaylord and Pallet remain in the Tipper.



Loading The Product

- 2. Close the gate and latch the **Catch Pin** to the Tipper.
- 3. Press the button to allow the **Foot Pedal** to be used.
- 4. Use the **Foot Pedal** on the step to raise and lower the Tipper to dump the product onto the belt.


Example Items That Need To Be Removed During Sorting:

- · Stuffed animals
- Shoes
- Hangers
- Plastic/plastic bags
- · Other non-cloth items



While Sorting:

The Baler will automatically compress the bale with the Ram (compression from the back towards the door) and Stamper (compression from the top down).



SAFETY ALERT:

DO NOT add any step, box, or other items to the sorting stands to aid in use or to use for decoration.


Baling Completion

From the Bale Complete Screen:

- 1. When the alarm sounds that a bale is complete, silence the alarm by pressing the **Silence Bale Comp Horn** button and then follow the steps for tying the bale.
- 2. Turn off the conveyor by pressing the **Conveyor Enabled** button, turning it blue.

From the Manual Control Screen:

3. Press the Manual Off button and wait until you hear the Baler turn back on in manual mode.






Tying The Bale

- 1. Push the baling wire down the back of the bale. The wire will go down the back and out front through the bottom.
- 2. Insert the looped end of the baling wire through the front.
- 3. Once you've inserted the wires, it will look like this from the front of the Baler.









Tying The Bale

- 4. From the front, grab the looped end of a bale wire, then take the straight end and put it through the loop. Using your body strength, pull the straight wire as tight as possible
- 5. When you have pulled it as tight as possible, wrap the straight end of the wire around the looped end of the wire <u>at least three times</u>. Wrap the remaining end of the wire around the back side of the wire to keep the end of the wire from sticking out and hurting someone during transport.








(Fully tied bale with the door open)

Removing The Bale

From the Manual Control Screen:

- 1. Press the **Open Door** button to open the door.
- 2. Once the door is opened, allow the forklift to line up bale in the opening.
- 3. When the forklift is in place, press the **Ram Forward** button until the bale is completely out of the Baler.
- 4. After the forklift drives away, ensure everyone is clear and press the **Close Door** button.
- 5. Press the **Ram Retract** button to retract the Ram.





Weighing The Bale

Weighing and documenting the bale:

- 1. Place the bale on the scale.
- 2. Each bale should weigh between 1000 and 1350 lbs.
- 3. Complete the "Recyclables Shipping Report" with the date and weight.





20,30							
- Contraction		Rec	yclables Ship	ping Report	-		
	DATE	1240 8	Weight	CIATE	GHE #	Weight	
	10/1		1165	10/5	18.	1272	
-	10/1		/239	10/5	19	1137	
	10/9		1222	1015	20	1265	
	10/3		1265	10/5	- 21	1/74	
	10/3		12/0	10/5	22	1/74	
	10/2		1193	10/6	177	1326	
	10/9		1184		24		
1	10/3	1	1246		25		
4	19/9	8.	1289		. 26		
V	10/5	10	1300		27		
0	10/3		1215		28		
	10/4	12	1296		28		
	10/4		1286		38		1
	10/4	14	1297		31		1
	10/5	15	1283		32		1
	10/5	16	/374				1
	10/5		1237		-		-
	1013	17	1001				

Baler Shut Down

Shut down, if applicable:

- 1. Press the Auto On button to shut off the Baler.
- 2. Turn the **Baler Key** to *Off*
- 3. Turn the **Baler Toggle Switch** to *Off* (90° clockwise).





